





## NOTES

## FIELD WIRING NOTES

1. ALL FIELD WIRING MUST BE DONE IN COMPLIANCE WITH ALL APPLICABLE LOCAL AND NATIONAL CODES.
2. CONNECT INCOMING POWER LEADS FROM POWER SUPPLY TO L1 AND L3 IN COMPRESSOR CONTACTOR (L1 AND L2 IF TWO POLE CONTACTOR) OR TO L1 AND L3 IN DISCONNECT SWITCH (IF PROVIDED). USE COPPER CONDUCTORS ONLY. (EMPLOYEUR DES CONDUCTEURS DE CUIVRE SEULEMENT.) PROVIDE EQUIPMENT GROUNDING CONDUCTOR. USE 75° C (MIN.) WIRING
3. PLACE JUMPER ACROSS P1 AND P2 IN TERMINAL BOARD IF NO OTHER CONTROLLING DEVICE IS INSTALLED.
4. DEFROST HEATERS LOADS SHOULD NOT BE HIGHER THEN THE MAXIMUM HEATERS LOAD INDICATED ON THE UNIT LABEL.
5. DEFROST TIMER IS INTERMATIC DTA40 OR PARAGON 8145-00.
6. IF DEFROST TIMER, LLS & T\*STAT ARE LOCATED IN EVAPORATOR, THEN SUPPLY POWER FROM P2 & P4 FROM THE TERMINAL BOARD.

GENERAL NOTES:

- A. CONTACTOR COIL CIRCUIT IS FACTORY CONNECTED IN PANEL AS SHOWN.  
B. WITH ANY T.P.Co. APPROVED START RELAY USED, CONNECT LEADS TO SAME NUMBERED TERMINALS REGARDLESS OF LOCATION.  
C. COMPRESSOR EQUIPPED WITH AN EXTERNAL OVERLOAD PROTECTOR. ALLOW TIME FOR RESET.



## CONDENSING UNIT WIRING


|          |         |          |
|----------|---------|----------|
| M        | 16JUN21 | PART NO. |
| REVISION |         | 91292    |

NOTES:

1. REDUCE WHEN PRINTING WITH BORDER LINE OF APPROX.  $7.75 \times 10.75$
- (C) 2. MATERIAL: Z-ULTIMATE 3000 WHITE.
- (C) 3. PRINTING TO BE IN COLOR WITH HEAVY ENOUGH PEN WEIGHT AND UL APPROVED INK.
- ▲ 4. MUST COMPLY WITH T.P.CO. GLOBAL SPEC 08.
- (M) 5. SEE SHEET 2 FOR PRODUCTION PRINTABLE VERSION.

3D.VNX1C

ENGLISH



|              |
|--------------|
| Q.A. SYMBOLS |
|--------------|

-  = CATEGORY I  
 = CATEGORY II  
 = CATEGORY III  
 = CATEGORY IV


UNIT

[illegible]

M

COMPRESSOR EQUIPPED WITH AN EXTERNAL OF INTERNAL  
OVERLOAD PROTECTOR. ALLOW TIME FOR RESET.  
USE COPPER CONDUCTORS ONLY.  
(EMPLOYER DES CONDUCTEURS DE CUIVER SEULEMENT.)

- FIELD INSTALLED LEAD  
AS REQUIRED




## NOTES

## FIELD WIRING NOTES

1. ALL FIELD WIRING MUST BE DONE IN COMPLIANCE WITH ALL APPLICABLE LOCAL AND NATIONAL CODES.
2. CONNECT INCOMING POWER LEADS FROM POWER SUPPLY TO L1 AND L3 IN COMPRESSOR CONTACTOR (L1 AND L2 IF TWO POLE CONTACTOR) OR TO L1 AND L3 IN DISCONNECT SWITCH (IF PROVIDED). USE COPPER CONDUCTORS ONLY. (EMPLOYER DES CONDUCTEURS DE CUIVRE SEULEMENT.) PROVIDE EQUIPMENT GROUNDING CONDUCTOR. USE 75° C (MIN.) WIRING
3. PLACE JUMPER ACCROSS P1 AND P2 IN TERMINAL BOARD IF NO OTHER CONTROLLING DEVICE IS INSTALLED.
4. DEFROST HEATERS LOADS SHOULD NOT BE HIGHER THEN THE MAXIMUM HEATERS LOAD INDICATED ON THE UNIT LABEL.
5. DEFROST TIMER IS INTERMATIC DTA4V0 OR PARAGON 8145-00.
6. IF DEFROST TIMER, LLS & T\*STAT ARE LOCATED IN EVAPORATOR, THEN SUPPLIER POWER FROM P2 & P4 FROM THE TERMINAL BOARD.

GENERAL NOTES:

- A. CONTACTOR COIL CIRCUIT IS FACTORY CONNECTED IN PANEL AS SHOWN.
- B. WITH ANY T.P.Co. APPROVED START RELAY USED, CONNECT LEADS TO SAME NUMBERED TERMINALS REGARDLESS OF LOCATION.
- C. COMPRESSOR EQUIPPED WITH AN EXTERNAL OVERLOAD PROTECTOR. ALLOW TIME FOR RESET.



## CONDENSING UNIT WIRING

|          |         |          |
|----------|---------|----------|
|          |         |          |
| M        | 16JUN21 | PART NO. |
| REVISION |         | 91292    |