


# Wiring Diagram



**Maximum Input Voltage** = 390 VAC RMS  
(maximum run cap volts)

**Input Voltage** = Run winding volts + start winding volts

**Note:** Run cap volts is higher than line voltage