Instructions for Using the Tear-Aid® Patch

Repairing General Tears and Holes

For best results, clean the surface to be repaired with an alcohol prep pad or 50/50 mix of rubbing alcohol and water making sure the surface is dry before proceeding.

Step 1 Cut a patch approximately 1 to 1.5 inches larger than the tear/hole to be repaired making sure the edges are rounded.

Step 2 Carefully peel back ½ inch of paper liner. Tearing the liner while stretching the patch's edge will help separate the two.

Step 3 Position the exposed ½ inch, making sure the patch extends 1 to 1.5 inches from all edges of the tear/hole. Slowly peel back the liner while carefully applying the patch over the tear. From the center the patch, press down and out to remove all air bubbles.

It is suggested that you wait 24 hours before re-inflating and using the product. If you want to speed this process, after the patch is applied, using a heat gun, heat briefly to a range of approximately 180° to 290° F. The heat time will vary depending on the size of the patch. Allow the product to cool before handling

© Copyright 2017
All rights reserved. No part of this publication may be reproduced or transmitted in any form or by any means, electronic or mechanical, including photocopy, recording, or any information storage and retrieval system, without permission in writing from the publisher. Requests should be mailed to RAVE Sports, 985 Aldrin Drive #301, Eagan MN, 55121



WWW.RAVESPORTS.COM

RAVE SPORTS
A Revel Match, LLC Company
985 Aldrin Drive #301
Eagan MN, 55121
800.659.0790

June 2017