ChargePort Pro | TA-7820US/TA-7820U

teleadapt

Desktop Mounting Plate - Screw Fixing

1. Mounting plate pack includes 2 small black screws and 2 larger black screws.

2. Install the black metal base plate in the desired location on the desktop using the 2 larger screws.

3. Finally, locate the ChargePort Pro on the mounting plate and then use the 2 small black screws to secure the ChargePort Pro to the mounting plate.

Note: Unit illustrated is TA-7820U, however instructions apply to both TA-7820US and TA-7820U.

ChargePort Pro | Mounting Options

Desktop Mounting Plate - Adhesive Pad Fixing

1. Mounting plate pack includes 2 small black screws and mounting plate with attached adhesive pad.

2. Use the 2 small screw to attach the mouning plate to ChargePort Pro.

3. Remove the protective paper from the adhesive pad and locate the ChargePort Pro on the desk. Press down firmly with your hands to ensure good adhesion.

Note: Unit illustrated is TA-7820U, however instructions apply to both TA-7820US and TA-7820U.

ChargePort Pro | Mounting Options

Cable Clamp

1. Carefully place the cable clamp over the mains lead and secure to a suitable surface with screw provided.

Security Lanyard

1. Secure one end of the lanyard to the ChargePort Pro using the screw provided.

2. Attach the free end of the lanyard to the furniture as required with the other screw.

Note: Unit illustrated is TA-7820U, however instructions apply to both TA-7820US and TA-7820U.

ChargePort Pro | Mounting Options

Visit our website at: www.teleadapt.com