Ethnicraft

PI WALL DESK
ASSEMBLY INSTRUCTIONS FOR WALL DESK INSTALLATION

HARDWARE ENCLOSED

PIN SHELF 20X10 / 6 (3pcs)	JIG (1pc)

HARDWARE REQUIRED
(Not included in this package)

WALL SCREW M4x50 (8pcs)	WALL PLUG S4 (8pcs)

TOOLS REQUIRED
(Not included in this package)

| SCREW DRIVER	DRILL
PENCIL	LEVEL

! AS WALL MATERIALS VARY, SCREWS FOR FIXING TO WALL ARE NOT INCLUDED. FOR ADVICE ON SUITABLE SCREW SYSTEMS, CONTACT YOUR LOCAL SPECIALISED DEALER.

IN YOUR PACKAGE :

ASSEMBLY INSTRUCTIONS
HARDWARE (AS LISTED ABOVE)

PARTS TO BE INSTALLED
1. METAL HANGING BRACKETS (2 pcs)
2. SHELF SUPPORTS (2 pcs)
3. SHELVES (2 pcs)

① ② (R) ③ UPPER SHELF

② (L) ③ LOWER SHELF / DESK

NOTICE

| ✔	X2	20kg MAXIMUM LOAD EACH SHELF

SYMBOLS

| DIRECTION	NUMBER OF PERSONS NEEDED	USE HAND	USE DRILL	USE SCREWDRIVER TO TIGHTEN	USE PENCIL

Ethnicraft

PI WALL DESK
ASSEMBLY INSTRUCTIONS FOR WALL DESK INSTALLATION

A INSTALLING METAL HANGING BRACKET TO THE WALL


Y cm
$(Y = desired\ height)$

90°

1

2

3

- **ILLUSTRATION WITH BRICK WALL**
- **MAKE PENCIL MARKS WITHIN METAL HANGING BRACKET SCREW HOLES**
- **USE LEVEL FOR ALIGNMENT**
- **USE WALL PLUG (X4)**
- **USE SCREW M4X50 (X4)**
- **TIGHTEN FULLY**

B DETERMINE THE DISTANCE BETWEEN METAL HANGING BRACKETS

JIG ●

- **USE JIG**
- **USE GUIDELINES TO ENSURE VERTICAL ALIGNMENT**

Ethnicraft

PI WALL DESK
ASSEMBLY INSTRUCTIONS FOR WALL DESK INSTALLATION

C INSTALLING METAL HANGING BRACKET TO THE WALL

90°

Y cm

①

1

2

3

- USE LEVEL FOR ALIGNMENT
- ENSURE BOTH METAL HANGING BRACKETS ARE
  AT AN EQUAL HEIGHT
- USE WALL PLUG (X4)
- USE SCREW M4X50 (X4)
- TIGHTEN FULLY

✔   ✘

D INSTALLING SHELF SUPPORTS

② (R)

② (L)

PLEASE REFER TO THE CODE ATTACHED ON THE SHELF SUPPORTS
L = LEFT SIDE
R = RIGHT SIDE

Ethnicraft

PI WALL DESK
ASSEMBLY INSTRUCTIONS FOR WALL DESK INSTALLATION

E ATTACHING LOWER SHELF / DESK

LOWER SHELF / DESK

F ATTACHING UPPER SHELF

UPPER SHELF

USE PIN SHELF 20X10 / 6 (X3)