

## Lab Coat Dimensions

Minimum Finished Dimensions  
 Limited-Use and Disposable Protective Lab Coat

	(1)	(2)	(3)	(4)
Size	Chest	Sleeve from Center Back	Body Length	Sleeve Opening
Small (S)	24.80 63	29.92 76	37.40 95	7.09 18
Medium (M)	25.98 66	31.10 79	38.58 98	7.09 18
Large (L)	26.77 68	32.68 83	39.76 101	7.09 18
X-Large (XL)	27.56 70	33.86 86	40.94 104	7.09 18
XX-Large (XXL)	28.35 72	35.04 89	42.13 107	7.09 18
XXX-Large (XXXL)	29.13 74	36.22 92	43.31 110	7.09 18

NOTE: All upper dimensions are in inches.  
 All lower dimensions are in centimeters  
 Specifications Specifications

FIGURE 1.  
 Measurement Locations for Lab Coat

NOTE: The following numbers correspond to the numbers used in Figure 1.

(1). CHEST: Measure from 1 inch below the base of the armhole, across the chest from folded to folded edge.

(2). SLEEVE OUT SEAM LENGTH from CENTER BACK POINT: Measure from the center back point to the top edge of the sleeve end

(3). BODY LENGTH: Measure from the top of the neckline at the center back point to the crotch seam with the lab coat flat and front side up.

(4). SLEEVE OPENING: Flatten the sleeve and measure from one folded edge to the other folded edge at the sleeve

