

## My SpinWave Robot is dispensing too much solution in Mop Mode | Support


If you are experiencing too much solution being put onto your floor while your SpinWave robot is in Mop Mode, follow these steps to resolve:

Remove Clean Water Tank



- Check that the correct amount of water and BISSELL formula are in the Clean Water Tank
- Filling the water tank with incorrect formula could result in inconsistent flow rates and too much solution on your floor
- Re-seat Water Tank in robot until it clicks
- If you are using the BISSELL App, change the flow rate to a lower mode > Click the mode on the bottom of the Robot screen > Choose Low and then Apply
- o If **robot** is performing an Auto Clean it will default to the mid flow rate





- Has this resolved the issue?
- o Yes > Great! Glad we could get you back to cleaning!