

## ST-IV+/XPROII N - TTL Flash Trigger (Nikon) Firmware Instructions

1. Please update the firmware with PIXAPRO firmware update software G3. G3 can be downloaded from the [essentialphoto](http://essentialphoto.com) website.
2. To Check your current firmware version, press the "MENU" button and enter C.Fn menu after turning the speedlite. The firmware version (e.g. Version xx will read U xx) will be displayed on the LCD screen.

Version	Update Comment	Release Date
V1.2	<ol style="list-style-type: none"> <li>1. To fix the occasional startup issue of the ST-IV+/XProII-N when the battery voltage is low.</li> <li>2. Resolve the issue of the AD600M being triggered only once when the flash trigger is activated.</li> </ol>	01/06/2023
V1.1	<ol style="list-style-type: none"> <li>1. Optimise the power-on communication logic of the Bluetooth module.</li> </ol>	14/04/2023
V1.0	<ol style="list-style-type: none"> <li>1. Original Version</li> </ol>	

Note: For more information, please download the latest version of the instruction manual from the "Downloads" tap of the product listing on the [essentialphoto.co.uk](http://essentialphoto.co.uk) website.