

X1R-S 索尼 接收器固件说明

- 一、请使用神牛固件升级软件 G3 打开该固件进行升级。G3 可在官网下载。
- 二、版本号查看方法：在接收器关机状态下按住 “GR” 按键不放，然后开机，此时液晶屏显示软件版本号（如 10 版本：10U）。
- 三、版本说明：

版本	更新内容	日期
V05	1、用户可设置 RF ID。方式：同时按住 CH 和 GR 按钮开机，进入 RF ID 设置界面，短按或长按 CH 按钮，增大 ID 值；短按或长按 GR 按钮，减少 ID 值。等待 5s 后关机，ID 值已设置并保存。正常开机，ID 值影响 RF 接收。 2、修复一些小问题。	2022-05-12
V04	1、修复顶部安装单触点机顶灯时不能正确引闪的问题。 2、修复通过同步口外接灯时不能正确引闪的问题。	2017-10-31
V03	1、初始版本。	2017-08-19

注：详细规格请在官网（www.godox.com.cn）下载最新说明书。

X1R-S Receiver (For Sony) Firmware Instructions

1. Please update the firmware with Godox firmware update software G3. G3 can be downloaded from the official website.
2. To check the version number, follow these steps: With the receiver powered off, press and hold the "GR" button, then power on the receiver. The LCD screen will display the software version number (e.g., for version 10: 10U).
3. Version Information:

Version	Updated Contents	Date
V05	1. Added Feature: User-Settable RF ID. Procedure: Power on the receiver by simultaneously holding down the CH and GR buttons. Enter the RF ID setting interface. Short or long press the CH button to increase the ID value; short or long press the GR button to decrease the ID value. After 5 seconds, power off the receiver to save the set ID value. Upon normal startup, the set ID value will affect RF reception. 2. Fixed some minor issues.	2022-05-12
V04	1. Fixed the issue where a single-contact camera flash could not trigger correctly when installed on the receiver.	2017-10-31

	2. Fixed the issue where the sync port did not correctly trigger the connected flash unit.	
V03	1. The Initial version.	2017-08-19

Note: For more details, please download the latest instruction manual from the official website:

<https://www.godox.com/>