




WARNING
 WIRING DIAGRAM MUST BE FOLLOWED AS SHOWN. ANY MISWIRING
 CAN CAUSE SERIOUS ELECTRICAL HAZARD AND POTENTIAL DAMAGE
 OR RUPTURE OF COMPONENT ELECTRICAL PARTS.



RK

DERK05