

Operating and Safety Instructions

POST HOLE BORER - ONE MAN

USES Boring holes in the ground



PRE CHECK

Fuel tank in full (2 Stroke 40:1 mix)
Correct quantity and sized shear pins
Correct auger for machine
Auger cutting tip is undamaged
Throttle lever returns by itself when released



STARTING

Fit the auger onto the machine
Turn on the fuel tap press priming bubble 3-4 times
Turn on the ignition switch
Move the choke lever to the closed position
Depress the throttle lever and engage throttle lock
Hold throttle handle with your left hand and pull starter cord with right hand
Give short sharp pulls until the engine fires or starts
Flick the throttle to disengage the throttle lock and let motor return to idle. Open the choke.



OPERATION

Grasp the machine firmly with both hands
Slightly spread feet apart to keep a good balance
Apply downward pressure onto the machine and depress throttle to a comfortable speed that suits
Keep drawing out the auger from the hole to clear the excavated earth



STOPPING

Allow the engine to cool down for two minutes
Depress stop button or turn off ignition switch to stop the engine
Turn off fuel tap



SAFETY PRECAUTIONS AND EQUIPMENT

Avoid wearing any loose clothing that may tangle in the auger
Use only in a well ventilated area
Securely hold the machine with both hands
Wear suitable clothing and footwear



HAZARDS

Avoid wearing any loose clothing that may tangle in the auger
Use only in a well ventilated area
Securely hold the machine with both hands
Wear suitable clothing and footwear

Personal Protective Equipment

