

## Big Green Deep Cleaning Machine® leaking from the bottom?

1. First, make sure the trigger isn't sticking.
2. Remove both tanks and make sure the bottom tank doesn't leak when it's removed. If it does leak, cap and tank will need to be replaced

### Leaking from the flow indicator:

If the cleaner leaks from the black and white flow indicator on the top of the machine need to be replaced.