




Accessory Code	PCS	Hardware Parts
A	4	
B	8	
C	48	
D	1	
E	16	
F	12	
G	12	

A standard slatted bed frame uses 11 support legs.

A folding slatted bed uses 12 support legs.

ITEM	Instructions
①	Install bed feet E at the head, edge, and tail of the bed
②	Install an A-angle iron with a C-screw to secure the headboard and bedside
③	Install B flat iron with a C screw to secure the edge and tail of the bed
④	Install foot F on the frame using G-screw washers and finally install the frame