

XProII-N 发射器固件说明

- 一、请使用神牛固件升级软件 G3 打开该固件进行升级。 G3 可在官网上下载。
- 二、版本号查看方法：发射器开机，按“MENU” 按键进入菜单设置，在屏幕右上角显示固件版本号（如 1.1 版本：V1.1）。
- 三、版本说明：

版本	更新内容	日期
V1.56	1、配合 XR 接收器进行的修改。 2、修复一些小问题。	2026-03-23
V1.5	1、修复了在 Z9, Z6III 相机上使用时，无法正常引闪的问题。 2、修复一些小问题。	2024-08-07
V1.4	1、修复在频闪模式下，快门速度不受限制的问题。	2024-08-07
V1.3	1、修复在单组设置界面，调入用户预设值后导致的显示错乱、不可切换组别的问题。	2023-07-19
V1.2	1、修复电池电压较低时，偶发的启动问题。 2、修复引闪 AD600M 只闪一次的问题。	2023-06-01
V1.1	1、优化蓝牙模块的开机通信逻辑。	2023-04-14
V1.0	初始版本	

注：详细规格请在官网（www.godox.com.cn）下载最新说明书。

XProII-N Firmware Release Note

1. Please use the G3 software, available for download on the Godox official website, to upgrade the XProII-N Firmware.
2. How to check the firmware version: Turn on the transmitter and go to the menu settings bypressing the "MENU" button. The firmware version will be shown in the upper right corner ofthe screen (e.g., version 1.1: V1.1).
3. Version Instructions:

Version	What's New	Date
V1.56	1. Updated for compatibility with the XR receiver. 2. Fixed some minor issues.	2026-03-23
V1.5	1.Fixed the issue where the Z9 and Z6III cameras could not trigger the flash properly. 2.Fixed some minor issues.	2024-08-07
V1.4	Fixed the issue where the shutter speed was not limited in stroboscopic (multi-flash) mode	2024-08-07
V1.3	Fixed the issue where, after loading user presets in the single-group settings interface, display errors occurred and group switching became impossible.	2023-07-19
V1.2	1. Fixed the occasional startup issue caused by low battery voltage. 2. Fixed the issue where the AD600M would only flash once.	2023-06-01
V1.1	Optimized the Bluetooth module's startup communication logic.	2023-04-14
V1.0	Original Version	

Note: For more details, please download the newest instruction manual on the official website: www.godox.com.